

No.	Description	Start date (gas day)	End date (gas day)	Days	Weeks	Impacted interconnection point							Technical capacity GWh/d		Available capacity during maintenance GWh/d		Remarks		
						Incukalns UGS	Vārška	Balticconnector	Kiemenai	Luhamaa	Klaipeda FSRU	Inkoo FSRU	Santaka	Entry	Exit	Entry		Exit	
1	Conexus - Gas transmission pipeline (GTP) Riga - Panevezys																		
1.2.	GTP Riga - Panevezys inspection based on diagnostics result, defect verification	06.04.2024	21.04.2024	16	14-16				X					90	82	0	0	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R003_001 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R004_001	
1.3.	Elimination of defects detected during inspection of the GTP Riga - Panevezys (pressure in the gas pipeline reduced to 20 bars)	03.08.2024	25.08.2024	23	31-34				X					90	82	0	0	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R005_001 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R006_001	
2	Conexus - GTP Viresi - Tallinn																		
2.2.	Elimination of defects detected during inspection of the GTP Viresi - Tallinn (pressure in the gas pipeline reduced to 20 bars)	01.07.2024	31.07.2024	31	27-31			X						78	65.4	5	0	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R009_001 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R010_001	
2.3.	GTP Viresi - Tallinn DN700 internal diagnostics	14.10.2024	27.10.2024	14	42-43			X						78	70.5	0	20	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=24032821X000000001379R001 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=24032821X000000001379R002	
3	Conexus - GTP Izborsk – Incukalns UGS																		
3.1.	GTP Izborsk – Incukalns UGS section repair works and restoration of anti-corrosion insulation	01.04.2024	30.04.2024	30	14-18					X				157.5	0	126	0	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R011_001 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-01-01&to=2029-04-06&ummid=23062121X000000001379R019_002 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R020_001	
3.2.	GTP Izborsk – Incukalns UGS section repair works and restoration of anti-corrosion insulation	01.05.2024	30.09.2024	153	19-40			X						78	65.4	75	50	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R012_001	
		01.05.2024	30.09.2024	153	19-40				X					178.5	0	105	0	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R013_001	
		01.10.2024	17.10.2024	17	40-42				X						160	0	105	0	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R015_002 https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R014_002
		18.10.2024	19.12.2024	63	42-52				X						105	105	105	30	
4	Conexus - Incukalns UGS																		
4.1.	Replacement of valves of compressor station No. 2, pipeline section repair works	21.10.2024	25.11.2024	36	43-49	X								246	51	147	51	https://transparency.entsoe.eu/#/umm/unavailabilitiesgasfacilities?from=2023-10-01&to=2029-04-06&ummid=23062121X000000001379R017_001	